



# 2003 Joint Service Scientific Conference on Chemical & Biological Defense Research November 2003

Robert Dinan & John Hawk

**Air Force Research Laboratory** 

Materials & Manufacturing
Directorate/Force Protection
Branch (MLQF)

**Tyndall AFB** 

(850)283-3605, DSN 523-3605

maintaining the data needed, and c including suggestions for reducing	lection of information is estimated to completing and reviewing the collect this burden, to Washington Headqu uld be aware that notwithstanding ar DMB control number.	ion of information. Send comments arters Services, Directorate for Infor	regarding this burden estimate mation Operations and Reports	or any other aspect of the 1215 Jefferson Davis	nis collection of information, Highway, Suite 1204, Arlington	
1. REPORT DATE 19 NOV 2003		2. REPORT TYPE N/A		3. DATES COVERED		
4. TITLE AND SUBTITLE				5a. CONTRACT NUMBER		
Survivability of Collective Protection Systems Subjected to Air I Loads				5b. GRANT NUMBER		
Loaus				5c. PROGRAM ELEMENT NUMBER		
6. AUTHOR(S)				5d. PROJECT NUMBER		
				5e. TASK NUMBER		
				5f. WORK UNIT NUMBER		
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)  Air Force Research Laboratory Materials & Manufacturing  Directorate/Force Protection Branch (MLQF) Tyndall AFB  8. PERFORMING ORGANIZATION REPORT NUMBER						
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)				10. SPONSOR/MONITOR'S ACRONYM(S)		
				11. SPONSOR/MONITOR'S REPORT NUMBER(S)		
12. DISTRIBUTION/AVAILABILITY STATEMENT  Approved for public release, distribution unlimited						
13. SUPPLEMENTARY NOTES  See also ADM001851, Proceedings of the 2003 Joint Service Scientific Conference on Chemical & Biological Defense Research, 17-20 November 2003., The original document contains color images.						
14. ABSTRACT						
15. SUBJECT TERMS						
16. SECURITY CLASSIFIC	17. LIMITATION OF ABSTRACT	18. NUMBER	19a. NAME OF			
a. REPORT unclassified	b. ABSTRACT <b>unclassified</b>	c. THIS PAGE unclassified	UU	OF PAGES 12	RESPONSIBLE PERSON	

**Report Documentation Page** 

Form Approved OMB No. 0704-0188









Tests conducted by the Air Force Research Laboratory (AFRL) and the USAF Force Protection Battlelab demonstrated that M28 liners installed in Tent Extendable Modular Personnel (TEMPER) tents ripped, separated at the zip connections, and failed to maintain pressure when subjected to blast loading by a satchel-sized explosive charge at standoff distances of 100 feet or more, while the parent tents suffered little or no damage at a standoff distance of 65 feet.









The M28 Collective Protection (CP) System is essentially a polyethylene liner used in TEMPER and other rigid frame tents. A filtered ventilation system supplies toxin free air to the liner and maintains a positive pressure slightly greater than the surrounding atmospheric pressure that ensures that the flow of air though small holes or loose seals is outward to prevent flow of contaminated air into the protective system. The TEMPER tent itself consists of a canvas material draped over a frame and staked to the ground.










The M28 liner system consists of 16 foot center sections, end sections, and entry vestibules that are joined by airtight zip-type seals.

Plastic straps with arrowhead type connectors riveted to the outside of the M28 liner attach to the tent frame to support the liner when it is not inflated by the ventilation system.









A tent fitted with the M28 collective protection system (CPS) allows personnel inside the shelter to work, eat or rest without the burden of individual protective equipment. However, this advantage is nullified if the liner has a breach so large that the ventilation system is unable to maintain positive pressure and outward air flow, as through a large tear or failure of a zip seal.





A satchel sized explosive device placed about 100 feet from TEMPER tents fitted with the M28 CPS did only minor damage to the tent and frame. Damage consisted primarily of stakes pulled from the ground and loosened tension lines.









The same satchel sized explosive device caused zip-seals in the M28 liner to separate, and resulted in a complete loss of positive pressure inside the liner.













Tears in the liner also contributed to the complete loss of overpressure inside the M28 liner after the explosive blast.





Tears are probably a result of the point stresses created where the arrowhead anchoring straps attach to the liner; as the liner is compressed by the pressure wave the anchor straps constrain the liner's motion.




Failure of the seals is likely due to the unequal distribution of pressure on the front and back side of the structure.









Data from tests on TEMPER tents with the M28 CPS highlights a significant shortcoming of the M28 liner; the survivability of the liner to air blast is not well balanced with the survivability of the parent tent.





- Partners at Virginia Tech are developing a computer model of the TEMPER-M28 system capable of predicting the response of the shelter to dynamic loads. Field tests are being conducted at AFRL to measure the response of the system to actual blast loads.
- The goal is to create a software model that can be used to analyze other softsided shelter systems, including future CPS designs, and to identify remedies to improve blast survivability of the existing TEMPER-M28 shelter.







- Collaborators
  - USAF Force Protection Battlelab
  - U.S. Army Soldier Systems Command
  - Virginia Polytechnic Institute and State University
  - Production Products Mfg. (manufacturer of the M28 liner)